

**DEFICIENCIES NOT INCLUDED IN OFFICIAL DEFICIENCY LIST**

1. Beams and lintels not plastered prior to painting.
2. Holes burned in steel columns for conduits.
3. Concrete in manhole, lintels, and trenches not properly rodded or vibrated.
4. Metal trench covers do not fit snugly and do not give level surface.
5. Paint scrapped off sides in numerous places and not repaired. (Exterior)
6. Fluorescent tubes missing.
7. Straighten light pole.
8. Floors not level prior to tiling.
9. Ground busses not set in a true straight line.
10. Tile not properly butted in control room (largely due to unlevel floor.)
11. Wood panel on which electrical panels are mounted in control room badly scarred.
12. Gray overhead buss in control room not neatly fitted.
13. Two damaged filters in north operating room.
14. Poor fabrication of intercom and telephone panel covers in control room.
15. Concrete and excess paint not removed from structural columns in control room prior to final painting.
16. Building structure bent in two places in north operating room.
17. Ceiling panels not properly fitted in many cases.
18. Glazing rough in some areas.
19. General lack of use of pipe sleeves.
20. CMU flashing strips in powerhouse not flush with wall.
21. Generator buss connected so that there was  $\frac{1}{2}$  inch between 240v buss and ground. (Sponsor will correct).